



Exercícios: Vistas Auxiliares

1)



2)



Isometric view of a mechanical part. Dimensions include: 40, 20, 20, 45°, 25, 10, R7.5, R22.5, and 135°.

Isometric view of a mechanical part. Dimensions include: 8, 30, 5.5, 10, 5.5, 10, 15, 20, 30, 38, 15, 8, 60, 5, 2, $\phi 28$, $\phi 40$, 20, $\phi 10$, 30, R15.